

Here is the Company Letter Certification Template to address if your company has decided to work under LBNL fall protection program. See attached Chapter 30 of our program of PUB 3000 for review. Your work plan will be written using the fall protection matrix system that must be signed by the responsible parties. Including each worker (Must possess Fall Protection Training) lead, supervisor, and signature of the Competent Person authorizing the anchorage, PFAS, and rescue plan. (EH&S fall protection Staff) will be glad to assist you with the completion of our fall protection matrix. All fall protection equipment will be inspected before work begins by LBNL SME of fall protection and all manufactures tags must be in tack and able to read.

The LBNL Fall Protection Matrix is a document that is for work at heights or unprotected edges equal to or greater than 6ft. This includes leading edges, tanks, manholes, unguarded machinery, aerial lifts, ladders, on slopes steeper than 2:1 (horizontal to vertical) roofs, and skylights. If erecting scaffolding and the erectors stand at 6 feet and above and your company has accepted the LBNL PUB 3000 Fall Protection Program in Chapter 30 a fall protection Matrix must be signed by the responsible parties. Including each worker (Must possess Fall Protection Training) the Matrix is a document that is for all work at heights or unprotected edges equal to or greater than 6ft. This includes leading scaffolds.